

Cgc

01272.020637



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

NOBUYUKI KUWABARA, et al.

Application No.: 10/671,619

Filed: September 29, 2003

For: INK SUPPLY SYSTEM, INK JET  
PRINTING APPARATUS, INK  
CONTAINER, INK REFILLING  
CONTAINER AND INK JET  
CARTRIDGE

U.S. Patent No.: 6,969,161 B2

Issued: November 29, 2005

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

)  
:  
Examiner: A. Vo

)  
:  
Group Art Unit: 2861

**Certificate**

**MAR 31 2006**

**of Correction**

)  
:  
March 28, 2006

CERTIFICATE OF CORRECTION UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

APR 03 2006

Patentees' undersigned attorney may be reached in our Costa Mesa,  
California office by telephone at (714) 540-8700. All correspondence should continue to  
be directed to our address given below.

Respectfully submitted,

A handwritten signature in cursive script, reading "Michael K. O'Neill". The signature is written in dark ink and is positioned above the printed name and title.

Attorney for Patentees  
Michael K. O'Neill  
Registration No.: 32,622

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200

CA\_MAIN 111279v1

APR 03 2006

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,969,161 *B2*  
DATED : November 29, 2005  
INVENTOR(S) : NOBUYUKI KUWA

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6

Line 33, "across-sectional" should read --a cross-sectional--; and  
Line 52, "sprint paper" should read --print paper--.

COLUMN 20

Line 18, "tube 13 is" should read --tube 13 and the ink level in the second ink container 125, (HS-Ha), is--.

COLUMN 24

Line 6, "consumed" should read --consumed.--; and  
Line 9, "head" should read --head.--.

COLUMN 27

Line 66, "tube" should read --tube.--.

COLUMN 30

Line 36, "wit" should read --with--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,969,161

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30)

CA\_MAIN 111281 v1



APR 03 2006

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,969,161 *B2*  
DATED : November 29, 2005  
INVENTOR(S) : NOBUYUKI KUWA

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6

Line 33, "across-sectional" should read --a cross-sectional--; and  
Line 52, "sprint paper" should read --print paper--.

COLUMN 20

Line 18, "tube 13 is" should read --tube 13 and the ink level in the second ink container 125, (HS-Ha), is--.

COLUMN 24

Line 6, "consumed" should read --consumed.--; and  
Line 9, "head" should read --head.--.

COLUMN 27

Line 66, "tube" should read --tube.--.

COLUMN 30

Line 36, "wit" should read --with--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,969,161

No. of add'l. copies  
@ 30¢ per page

APR 03 2006